




Proof of service 1

The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	ATF	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service interval display incl. engine oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Inspection service	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Brake fluid change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input checked="" type="checkbox"/>
LongLife engine oil used	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: Oil	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Date: 1/16/12			Fuel filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Km (miles): 16350			Air filter insert	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Invoice number:			Tyre pressure sensors	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Dust and pollen filter insert	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Customer request	<input type="checkbox"/>	<input type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by:			LongLife mobility guarantee:		
 <p>210 354 Ridgeway Garages Ltd Newbury Motor Park The Triangle Newbury RG14 7HT Tel:- 01635 40678 Fax:- 01635 523804</p>					
Volkswagen dealership stamp			Volkswagen dealership stamp		


Proof of service 2

The following jobs were done:		Yes	No	Additional work - Change of:		Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
In combination	<input checked="" type="checkbox"/>	<input type="checkbox"/>	ATF	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Service interval display incl. engine oil change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
In combination	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Inspection service	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Brake fluid change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
LongLife engine oil used	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Date:	13/04/13		Fuel filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Km (miles):	25986		Air filter insert	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Invoice number:	64358		Tyre pressure sensors	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Repair recommendation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Customer request	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Dust and pollen filter insert	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
(Please note this on the order.)			Toothed belt	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Service carried out by:			Spark plugs	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
 210 354 Ridgeway Garages Ltd Newbury Motor Park The Triangle Newbury RG14 7HT Tel:- 01635 40678 Fax:- 01635 523804				LongLife mobility guarantee:			
Volkswagen dealership stamp				Volkswagen dealership stamp			


Proof of service 3

The following jobs were done:		Yes	No	Additional work - Change of:		Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
In combination	<input type="checkbox"/>	<input checked="" type="checkbox"/>	ATF	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service interval display incl. engine oil change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Inspection service	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Brake fluid change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
LongLife engine oil used	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Date: 8/6/13			Fuel filter	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Km (miles): 2900			Air filter insert	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Invoice number: 11675			Tyre pressure sensors	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Customer request	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Dust and pollen filter insert	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(Please note this on the order.)			Toothed belt	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service carried out by:			Spark plugs	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
 210 354 Ridgeway Garages Ltd Newbury Motor Park The Triangle Newbury RG14 7HT Tel:- 01635 40678 Fax:- 01635 523804			LongLife mobility guarantee:				
Volkswagen dealership stamp			Volkswagen dealership stamp				

Proof of service 4

The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input checked="" type="checkbox"/>	ATF	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service interval display incl. engine oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Inspection service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Brake fluid change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input checked="" type="checkbox"/>
LongLife engine oil used	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Date: 15/02/14			Fuel filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Km (miles): 38526			Air filter insert	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Invoice number: WIP 22753			Tyre pressure sensors	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Dust and pollen filter insert	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Customer request	<input type="checkbox"/>	<input type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by:			LongLife mobility guarantee:		
 210 354 Ridgeway Garages Ltd Newbury Motor Park The Triangle Newbury RG14 7HT Tel:- 01635 40678 Fax:- 01635 523804					
Volkswagen dealership stamp			Volkswagen dealership stamp		

Proof of service 5

The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input checked="" type="checkbox"/>	ATF	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service interval display incl. engine oil change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Inspection service	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Brake fluid change	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input checked="" type="checkbox"/>
LongLife engine oil used	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Date: 17/11/14			Fuel filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Km (miles): 47871			Air filter insert	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Invoice number: 35852			Tyre pressure sensors	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Dust and pollen filter insert	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Customer request	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by:			LongLife mobility guarantee:		
 210 354 Ridgeway Garages Ltd Newbury Motor Park The Triangle Newbury Berks RG14 7HT Tel:- 01635 40678			<i>Any belt + tensioner and water pump + BFC. Done on 16/11/15 @ 55987</i>		

Volkswagen dealership stamp

Volkswagen dealership stamp


Proof of service 6

FULL SERVICE + REAR PADS


The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	ATF	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service interval display incl. engine oil change	<input type="checkbox"/>	<input type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Inspection service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Brake fluid change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input checked="" type="checkbox"/>
LongLife engine oil used	<input type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Date: 28/9/15			Fuel filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Km (miles): 57320			Air filter insert	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Invoice number:			Tyre pressure sensors	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Dust and pollen filter insert	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Customer request	<input type="checkbox"/>	<input type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by:			LongLife mobility guarantee:		
RAYNER BOSCH CAR SERVICE UNIT 5, 36 QUEENS ROAD NEWBURY BERKS. RG14 7NE TELEPHONE (01635) 46323			RAYNER BOSCH CAR SERVICE UNIT 5, 36 QUEENS ROAD NEWBURY BERKS. RG14 7NE TELEPHONE (01635) 46323		
Volkswagen dealership stamp			Volkswagen dealership stamp		

Proof of service 7


Inspection service

The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	ATF	<input type="checkbox"/>	<input type="checkbox"/>
Service interval display incl. engine oil change	<input type="checkbox"/>	<input type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input type="checkbox"/>
Inspection service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input type="checkbox"/>
Brake fluid change	<input type="checkbox"/>	<input type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input type="checkbox"/>
LongLife engine oil used	<input type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input type="checkbox"/>
Date: 28/10/16			Fuel filter	<input type="checkbox"/>	<input type="checkbox"/>
Km (miles): 66219			Air filter insert	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Invoice number: 54969			Tyre pressure sensors	<input type="checkbox"/>	<input type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input type="checkbox"/>
			Dust and pollen filter insert	<input type="checkbox"/>	<input type="checkbox"/>
Customer request	<input type="checkbox"/>	<input type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by: 			LongLife mobility guarantee:		
RAYNER BOSCH CAR SERVICE UNIT 5, 36 QUEENS ROAD NEWBURY BERKS. RG14 7NE TELEPHONE (01635) 46323			RAYNER BOSCH CAR SERVICE UNIT 5, 36 QUEENS ROAD NEWBURY BERKS. RG14 7NE TELEPHONE (01635) 46323		
Volkswagen dealership stamp			Volkswagen dealership stamp		


Proof of service 8

The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input checked="" type="checkbox"/>	<input type="checkbox"/>	ATF	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service interval display incl. engine oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Inspection service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Brake fluid change	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input checked="" type="checkbox"/>
LongLife engine oil used	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Date: 18/03/2020			Fuel filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Km (miles): 85,393			Air filter insert	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Invoice number:			Tyre pressure sensors	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Repair recommendation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Dust and pollen filter insert	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Customer request	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by:			LongLife mobility guarantee:		
			Rayner Diesel Services Unit 5 36 Queens Road Newbury Berkshire RG14 7NE 01635 46323 www.raynerdiesel.co.uk info@raynerdiesel.co.uk		
Volkswagen dealership stamp			Volkswagen dealership stamp		

Proof of service 9

The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	ATF	<input type="checkbox"/>	<input type="checkbox"/>
Service interval display incl. engine oil change	<input type="checkbox"/>	<input type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input type="checkbox"/>
Inspection service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input type="checkbox"/>
Brake fluid change	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input type="checkbox"/>
LongLife engine oil used	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input type="checkbox"/>
Date: 17/12/21			Fuel filter	<input type="checkbox"/>	<input type="checkbox"/>
Km (miles): 91278			Air filter insert	<input type="checkbox"/>	<input type="checkbox"/>
Invoice number:			Tyre pressure sensors	<input type="checkbox"/>	<input type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input type="checkbox"/>
			Dust and pollen filter insert	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Customer request	<input type="checkbox"/>	<input type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by:			LongLife mobility guarantee:		
 MOTORS RG20 OPW 01635 254607					
Volkswagen dealership stamp			Volkswagen dealership stamp		

Proof of service 10

The following jobs were done:	Yes	No	Additional work - Change of:	Yes	No
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	AdBlue®	<input type="checkbox"/>	<input type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	ATF	<input type="checkbox"/>	<input type="checkbox"/>
Service interval display incl. engine oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>	DSG®: oil and filter	<input type="checkbox"/>	<input type="checkbox"/>
In combination	<input type="checkbox"/>	<input type="checkbox"/>	Natural gas tank and pipelines	<input type="checkbox"/>	<input type="checkbox"/>
Inspection service	<input type="checkbox"/>	<input type="checkbox"/>	Liquid gas filter (paper filter)	<input type="checkbox"/>	<input type="checkbox"/>
Brake fluid change	<input type="checkbox"/>	<input type="checkbox"/>	Gas filter and hoses	<input type="checkbox"/>	<input type="checkbox"/>
LongLife engine oil used	<input type="checkbox"/>	<input type="checkbox"/>	Haldex coupling: oil	<input type="checkbox"/>	<input type="checkbox"/>
Date: 9/2/24			Fuel filter	<input type="checkbox"/>	<input type="checkbox"/>
Km (miles): 100738			Air filter insert	<input type="checkbox"/>	<input type="checkbox"/>
Invoice number:			Tyre pressure sensors	<input type="checkbox"/>	<input type="checkbox"/>
Repair recommendation	<input type="checkbox"/>	<input type="checkbox"/>	Tyre filler bottle	<input type="checkbox"/>	<input type="checkbox"/>
			Dust and pollen filter insert	<input type="checkbox"/>	<input type="checkbox"/>
Customer request	<input type="checkbox"/>	<input type="checkbox"/>	Toothed belt	<input type="checkbox"/>	<input type="checkbox"/>
			Spark plugs	<input type="checkbox"/>	<input type="checkbox"/>
(Please note this on the order.)				<input type="checkbox"/>	<input type="checkbox"/>
Service carried out by:	LongLife mobility guarantee:				
 MOTORS RG20 OPW 01635 254607					
Volkswagen dealership stamp			Volkswagen dealership stamp		