


# Vehicle data

1	WVWZZZ6RzFY094708											
2	6C1 BNX											
	POLO 1.4 BMT BL GT											
3	110 M6F											
	CZE					NJU						
4	LD5L					RU						
	1AZ Q16											
	7MM		CD2		H5V		4KC		3NC			
	2FS		Q4H		JOS		8K3		8M1			
	8ID		UOL		BRL		8TD		8WH			
	1BE											


BTT-0507

**Fig. 1** 1: Vehicle identification number; 2: Vehicle type, engine power, gearbox type; 3: Engine code, gearbox code, paint number, interior equipment; 4: Optional extras, PR numbers

<p>Delivery inspection carried out on: <i>31/7/14</i></p>	<p>Date of delivery to customer / initial registration:<sup>a)</sup></p>
 <p>210                      653  <b>Inchcape Volkswagen Bolton</b>          Morris Street          Mill Street Industrial Estate          Bolton BL2 2BL          Tel:- 01204 531464          Fax:- 01204 364835</p>	
Volkswagen dealership stamp	Volkswagen dealership stamp

a) Whichever comes first.

# Proof of service 1

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input type="checkbox"/> / <input checked="" type="checkbox"/> Oil change service	<input type="checkbox"/> / <input checked="" type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> / <input type="checkbox"/> With oil change	<input type="checkbox"/> / <input checked="" type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gas filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> / <input type="checkbox"/> Body check	<input type="checkbox"/> / <input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input type="checkbox"/> Repairs recommended	<input type="checkbox"/> / <input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> / <input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> / <input checked="" type="checkbox"/> Tyre filler bottle (sealant)
Service carried out on: 1.6.16  at km/miles: 18755	<input checked="" type="checkbox"/> / <input type="checkbox"/> Dust and pollen filter insert
	<input type="checkbox"/> / <input checked="" type="checkbox"/> Toothed belt
	<input type="checkbox"/> / <input checked="" type="checkbox"/> Spark plugs
Invoice number:	<input type="checkbox"/> / <input type="checkbox"/> .....
Service carried out by:	LongLife mobility guarantee:
 210 653 Inchcape Volkswagen Bolton Morris Street Mill Street Industrial Estate Bolton BL2 2BL Tel:- 01204 531464 Fax:- 01204 364835	Volkswagen dealership stamp
Stamp of qualified workshop	

## Your next service


### Service event

as per Service interval display  
 or  
 on (Date): 1.6.17  
 or  
 at (km/miles): 28755

### Additional work


.....  
 on (Date): .....  
 or  
 at (km/miles): .....

# Proof of service 2

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> / <input type="checkbox"/> Oil change service	<input type="checkbox"/> / <input checked="" type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input checked="" type="checkbox"/> / <input type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> / <input type="checkbox"/> With oil change	<input type="checkbox"/> / <input checked="" type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gas filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> / <input checked="" type="checkbox"/> Body check	<input type="checkbox"/> / <input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input checked="" type="checkbox"/> Repairs recommended	<input type="checkbox"/> / <input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> / <input checked="" type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> / <input checked="" type="checkbox"/> Tyre filler bottle (sealant)
Service carried out on: <b>14-7-17</b>	<input type="checkbox"/> / <input checked="" type="checkbox"/> Dust and pollen filter insert
at km/miles: <b>28,118</b>	<input type="checkbox"/> / <input checked="" type="checkbox"/> Toothed belt
Invoice number:	<input type="checkbox"/> / <input checked="" type="checkbox"/> Spark plugs
Service carried out by:	<input type="checkbox"/> / <input type="checkbox"/> .....
 210 653 Inchcape Volkswagen Bolton Morris Street Mill Street Industrial Estate Bolton BL2 2BL Tel:- 01204 531464 01204 5364835	LongLife mobility guarantee:          Volkswagen dealership stamp



Your next service	
Service event	Additional work
<input type="checkbox"/> as per Service interval display or on (Date): <b>14-7-18</b> or at (km/miles): <b>38,118</b>	..... on (Date): ..... or at (km/miles): .....

# Proof of service 3

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> / <input type="checkbox"/> Oil change service	<input checked="" type="checkbox"/> / <input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input checked="" type="checkbox"/> / <input type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> / <input type="checkbox"/> With oil change	<input checked="" type="checkbox"/> / <input type="checkbox"/> Diesel fuel filter
<input checked="" type="checkbox"/> / <input type="checkbox"/> With extended scope of inspection	<input checked="" type="checkbox"/> / <input type="checkbox"/> Gas filter
<input checked="" type="checkbox"/> / <input type="checkbox"/> LongLife engine oil used	<input checked="" type="checkbox"/> / <input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> / <input type="checkbox"/> Body check	<input checked="" type="checkbox"/> / <input type="checkbox"/> Haldex coupling: oil
<input checked="" type="checkbox"/> / <input type="checkbox"/> Repairs recommended	<input checked="" type="checkbox"/> / <input type="checkbox"/> Air filter insert
<input checked="" type="checkbox"/> / <input type="checkbox"/> Customer request (this should also be noted on the order)	<input checked="" type="checkbox"/> / <input type="checkbox"/> Tyre filler bottle (sealant)
Service carried out on: 10.8.18.	<input checked="" type="checkbox"/> / <input type="checkbox"/> Dust and pollen filter insert
at km/miles: 75,793	<input checked="" type="checkbox"/> / <input type="checkbox"/> Toothed belt
Invoice number:	<input checked="" type="checkbox"/> / <input type="checkbox"/> Spark plugs
Service carried out by:	<input type="checkbox"/> / <input type="checkbox"/> .....
 210 653 Inchcape Volkswagen Bolton Morris Street Mill Street Industrial Estate Bolton BL2 2BL Tel:- 01204 531464 Fax:- 01204 364835	LongLife mobility guarantee:
Stamp of qualified workshop	Volkswagen dealership stamp


Your next service	
Service event	Additional work
<input checked="" type="checkbox"/> as per Service interval display	
or	.....
on (Date): .....	on (Date): .....
or	or
at (km/miles): .....	at (km/miles): .....

# Proof of service 4

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input type="checkbox"/> / <input type="checkbox"/> Oil change service	<input type="checkbox"/> / <input checked="" type="checkbox"/> AdBlue® 
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Brake fluid + AC Service
<input checked="" type="checkbox"/> / <input type="checkbox"/> With oil change	<input type="checkbox"/> / <input checked="" type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> / <input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gas filter
<input type="checkbox"/> / <input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> / <input type="checkbox"/> Body check	<input type="checkbox"/> / <input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input checked="" type="checkbox"/> Repairs recommended	<input type="checkbox"/> / <input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> / <input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> / <input checked="" type="checkbox"/> Tyre filler bottle (sealant)
Service carried out on: 01-08-19	<input type="checkbox"/> / <input checked="" type="checkbox"/> Dust and pollen filter insert
at km/miles: 42083	<input checked="" type="checkbox"/> / <input type="checkbox"/> Toothed belt
Invoice number:	<input type="checkbox"/> / <input checked="" type="checkbox"/> Spark plugs
Service carried out by: 	<input type="checkbox"/> / <input type="checkbox"/> .....
210 653 Inchcape Volkswagen Bolton Morris Street Mill Street Industrial Estate Bolton BL2 2BL Tel:- 01204 531464 Fax:- 01204 364835	LongLife mobility guarantee:  Volkswagen dealership stamp


Your next service	
Service event	Additional work
<input type="checkbox"/> as per Service interval display	masor. on (Date): 08-20 or at (km/miles): .....
or	
on (Date): .....	
or	or
at (km/miles): .....	at (km/miles): .....

# Proof of service 5

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> / <input type="checkbox"/> Oil change service	<input type="checkbox"/> / <input checked="" type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input checked="" type="checkbox"/> / <input checked="" type="checkbox"/> Brake fluid
<input type="checkbox"/> / <input checked="" type="checkbox"/> With oil change	<input type="checkbox"/> / <input checked="" type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gas filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> / <input checked="" type="checkbox"/> Body check	<input type="checkbox"/> / <input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input checked="" type="checkbox"/> Repairs recommended	<input type="checkbox"/> / <input checked="" type="checkbox"/> Air filter insert
<input checked="" type="checkbox"/> / <input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> / <input checked="" type="checkbox"/> Tyre filler bottle (sealant)
Service carried out on: 24/09/21	<input type="checkbox"/> / <input checked="" type="checkbox"/> Dust and pollen filter insert
at km/miles: 47779	<input type="checkbox"/> / <input checked="" type="checkbox"/> Toothed belt
Invoice number: 319110	<input checked="" type="checkbox"/> / <input type="checkbox"/> Spark plugs
Service carried out by:	<input checked="" type="checkbox"/> / <input type="checkbox"/> ..... MOT
 210 653 Inchcape Volkswagen Bolton Morris Street Mill Street Industrial Estate Bolton BL2 2BL Tel: 01204 531464 Fax: 01204 364835	LongLife mobility guarantee:  Volkswagen dealership stamp


Your next service	
Service event	Additional work
<input type="checkbox"/> as per Service interval display or on (Date): ..... or at (km/miles): .....	..... on (Date): ..... or at (km/miles): .....

# Proof of service 6

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> / <input type="checkbox"/> Oil change service	<input type="checkbox"/> / <input checked="" type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input checked="" type="checkbox"/> / <input type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> / <input type="checkbox"/> With oil change	<input type="checkbox"/> / <input checked="" type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gas filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> / <input checked="" type="checkbox"/> Body check	<input type="checkbox"/> / <input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input checked="" type="checkbox"/> Repairs recommended	<input checked="" type="checkbox"/> / <input type="checkbox"/> Air filter insert
<input type="checkbox"/> / <input checked="" type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> / <input checked="" type="checkbox"/> Tyre filler bottle (sealant)
Service carried out on: 21.9.22	<input checked="" type="checkbox"/> / <input type="checkbox"/> Dust and pollen filter insert
at km/miles: 55,121	<input type="checkbox"/> / <input checked="" type="checkbox"/> Toothed belt
Invoice number: 47915	<input checked="" type="checkbox"/> / <input type="checkbox"/> Spark plugs
Service carried out by:	<input checked="" type="checkbox"/> / <input type="checkbox"/> MOT + A/c/s
 270 653 Inchcape Volkswagen Bolton Morris Street Mill Street Industrial Estate Bolton BL2 2BL Tel: 01204 531464 Fax: 01204 364835	LongLife mobility guarantee:
Stamp of qualified workshop	Volkswagen dealership stamp

Your next service	
Service event	Additional work
<input checked="" type="checkbox"/> as per Service interval display or on (Date): 9.23 or at (km/miles): 65,000	..... on (Date): ..... or at (km/miles): .....

# Proof of service 7

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> / <input type="checkbox"/> Oil change service	<input type="checkbox"/> / <input checked="" type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> / <input type="checkbox"/> With oil change	<input type="checkbox"/> / <input checked="" type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> / <input checked="" type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gas filter
<input checked="" type="checkbox"/> / <input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> / <input checked="" type="checkbox"/> Body check	<input type="checkbox"/> / <input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input checked="" type="checkbox"/> Repairs recommended	<input type="checkbox"/> / <input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> / <input checked="" type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> / <input checked="" type="checkbox"/> Tyre filler bottle (sealant)
Service carried out on: 08.05.24	<input type="checkbox"/> / <input checked="" type="checkbox"/> Dust and pollen filter insert
at km/miles: 72948	<input type="checkbox"/> / <input checked="" type="checkbox"/> Toothed belt
Invoice number:	<input type="checkbox"/> / <input checked="" type="checkbox"/> Spark plugs
Service carried out by:	<input type="checkbox"/> / <input type="checkbox"/> .....
 <p><b>ROY WINDEBANK AUTO ENGINEERS LTD 01491 652345</b></p>	LongLife mobility guarantee:
Stamp of qualified workshop	Volkswagen dealership stamp

Your next service	
Service event	Additional work
<input type="checkbox"/> as per Service interval display	
or	.....
on (Date): .....	on (Date): .....
or	or
at (km/miles): .....	at (km/miles): .....