

Date	Service Centre	Line Item Description
07 Jan 2020	ATS CH ARVAL DEALERS	P 1 Michelin 255/35 R 19 Y PIL SPT3 ZPXL (EA2-73dB)
Odo Reading	38058	P 1 Casing Disposal
Invoice No.	10779759	P 1 Wheel Balance
Authority Ref.		P 1 Tubeless Valve
Job Ref.	7086599	
Job Status	Complete	

Date	Service Centre	Line Item Description
01 Aug 2018	MOBILE WINDSCREENS LIVERPOOL	P 1 2465AGSMV2P
Odo Reading	20915	
Invoice No.	B780683	
Authority Ref.		
Job Ref.	5550999	
Job Status	Complete	

Date	Service Centre	Line Item Description
04 May 2018	Williams Liverpool BMW	Service - standard scope
Odo Reading	16919	Microfilter service
Invoice No.		Engine oil service
Authority Ref.		
Job Ref.	126457998	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
12 Dec 2017	MOBILE WINDSCREENS LIVERPOOL	P 1 2465LGNS4FD
Odo Reading	11000	
Invoice No.	B583396	
Authority Ref.		
Job Ref.	5155786	
Job Status	Complete	

Date	Service Centre	Line Item Description
04 Feb 2021	Williams Liverpool BMW	Disc - Remove & Refit, Disc - front (pair)
Odo Reading	46848	Service - Standard Scope - 2011/19 3 Series (F30/F34/F31)
Invoice No.	25440436	Disc - Remove & Refit, Disc - rear (pair)
Authority Ref.	7863739	Door (Rear) - Remove & Refit, Door (rear) - window channels (door set) right
Job Ref.	108652863	Checks - Check, Investigate & Report
Job Status	Payment Requested	Automatic Transmission Assembly - Remove & Refit, Oil pan (Auto. Trans.)

Date	Service Centre	Line Item Description
22 Dec 2020	ATS CH ARVAL DEALERS	P 1 Wheel Balance
Odo Reading	46268	P 1 Tubeless Valve
Invoice No.	10949319	P 1 Goodyear 255/35 R 19 Y EAGLEF1ASY2ROF (EB1-65dB)
Authority Ref.		P 1 Casing Disposal
Job Ref.	7562678	P 1 Wheel Balance
Job Status	Complete	P 1 Tubeless Valve
		P 1 Goodyear 225/40 R 19 Y EAG F1 ASM2 * FP ROF
		P 1 Casing Disposal

Date	Service Centre	Line Item Description
12 Mar 2020	Williams Liverpool BMW	Supply & Fit - N/S Front - Bridgestone 225/40 R19 89Y Potenza S001 RF
Odo Reading	39916	
Invoice No.	TY120031300008	
Authority Ref.	7605987	
Job Ref.	103530290	
Job Status	Settlement Requested	

Date	Service Centre	Line Item Description
06 Mar 2020	Williams Liverpool BMW	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:12 Mar 2020 Certificate No:145148656587
Odo Reading	39916	Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake)
Invoice No.	25415655	
Authority Ref.	7606445	
Job Ref.	103394524	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
05 Mar 2020	Williams Liverpool BMW	Service - standard scope
Odo Reading	39916	Service - air filter element
Invoice No.		Microfilter service
Authority Ref.		Brake fluid service
Job Ref.	126458300	Service, vehicle check
Job Status	Payment Requested	Engine oil service
		Service fuel filter

Date	Service Centre	Line Item Description
08 Sep 2022	ATS PENSBY (511)	P 1 Bridgestone 225/40 R 19 Y S001 *RF (EB2-71dB)
Odo Reading	69722	P 1 Wheel Balance
Invoice No.	11246625	P 1 Casing Disposal
Authority Ref.		P 1 Tubeless Valve
Job Ref.	9767123	P 1 Bridgestone 225/40 R 19 Y S001 *RF (EB2-71dB)
Job Status	Complete	P 1 Wheel Balance
		P 1 Casing Disposal
		P 1 Tubeless Valve

Date	Service Centre	Line Item Description
06 Sep 2022	ATS PENSBY (511)	P 1 Bridgestone 255/35 R 19 Y S001 * RF (EB2-72dB)
Odo Reading	69634	P 1 Wheel Balance
Invoice No.	11245001	P 1 Casing Disposal
Authority Ref.		P 1 Tubeless Valve
Job Ref.	9762730	P 1 Bridgestone 255/35 R 19 Y S001 * RF (EB2-72dB)
Job Status	Complete	P 1 Wheel Balance
		P 1 Casing Disposal
		P 1 Tubeless Valve

Date	Service Centre	Line Item Description
21 Feb 2022	Williams Liverpool BMW	Supply & Fit - O/S Rear - Bridgestone 255/35 R19 92Y Potenza S001 RFT
Odo Reading	61000	
Invoice No.	TYI22022200076	
Authority Ref.	8174511	
Job Ref.	115764278	
Job Status	Settlement Requested	

Date	Service Centre	Line Item Description
21 Feb 2022	Williams Liverpool BMW	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:21 Feb 2022 Certificate No:326525602447
Odo Reading	61904	Service - Standard Scope - 2011/19 3 Series (F30/F34/F31)
Invoice No.	25474989	3rd Oil Service - 2011/19 3 Series (F30/F34/F31)
Authority Ref.	8173751	Ventilation - Remove & Refit, Pollen filter
Job Ref.	115746191	brake fluid service - 2011/19 3 Series (F30/F34/F31)
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
15 Mar 2021	Williams Liverpool BMW	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:15 Mar 2021 Certificate No:737565497245
Odo Reading	47695	
Invoice No.	25443286	
Authority Ref.	7890855	
Job Ref.	109370576	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
14 Mar 2024	Halliwell Jones (Chester) Ltd BMW	MOT - Class IV Cars (Up To 8 Passenger Seats) Checks - Check, Investigate & Report
Odo Reading	91723	
Invoice No.		
Authority Ref.	8832207	
Job Ref.	133954815	
Job Status	Cancelled Job Sheet	

Date	Service Centre	Line Item Description
18 Dec 2023	Williams Liverpool BMW	Service - Standard Scope - 2011/19 3 Series (F30/F34/F31) 5th Oil Service - 2011/19 3 Series (F30/F34/F31)
Odo Reading	87123	
Invoice No.	25541864	
Authority Ref.	8755262	
Job Ref.	131582300	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
15 Jul 2023	ATS PENSBY (511)	P 1 Casing Disposal P 1 Wheel Balance P 1 Goodyear 225/40 R 19 Y YR EGF1ASY5 XL (BA1-69dB) P 1 Tubeless Valve P 1 Casing Disposal P 1 Wheel Balance P 1 Goodyear 225/40 R 19 Y YR EGF1ASY5 XL (BA1-69dB) P 1 Tubeless Valve
Odo Reading	80877	
Invoice No.	11402401	
Authority Ref.		
Job Ref.	10450171	
Job Status	Complete	

Date	Service Centre	Line Item Description
20 Mar 2023	Williams Liverpool BMW	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:21 Mar 2023 Certificate No:457683697850 4th Oil Service - 2011/19 3 Series (F30/F34/F31) Vehicle Check Service - 2011/19 3 Series (F30/F34/F31) Service - Standard Scope - 2011/19 3 Series (F30/F34/F31)
Odo Reading	76388	
Invoice No.	25514436	
Authority Ref.	8513588	
Job Ref.	124641201	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
30 Nov 2022	Williams Liverpool BMW	Cooling System - Check, Cooling system - pressure test Water Pump - Remove & Refit, Water pump drive belt
Odo Reading	72747	
Invoice No.	25504232	
Authority Ref.	8415022	
Job Ref.	122025851	
Job Status	Payment Requested	

Work History

Registration/Fleet ID	FE17WHX	Asset No.	AADF9339
Make/Model	BMW 3 SERIES DIESEL TOURING (2015) 335d xDrive M Sport 5dr Step Auto		
Latest Odo Reading	91723	Odo Reading Date	03 Apr 2024
Contract Start Date	19 Mar 2017	Contract End Date	18 Jun 2024

Date	Service Centre	Line Item Description
02 Apr 2024	Halliwell Jones (Chester) Ltd BMW	
Odo Reading	91723	
Invoice No.		
Authority Ref.		
Job Ref.	134403760	
Job Status	Cancelled Job Sheet	

Date	Service Centre	Line Item Description
26 Mar 2024	Williams Liverpool BMW	Checks - Check, Investigate & Report
Odo Reading	91759	Checks - Check, Investigate & Report
Invoice No.		brake fluid service - 2011/19 3 Series (F30/F34/F31)
Authority Ref.	8841751	Service - Standard Scope - 2011/19 3 Series (F30/F34/F31)
Job Ref.	134287699	
Job Status	Cancelled Job Sheet	

Date	Service Centre	Line Item Description
19 Mar 2024	Halliwell Jones (Chester) Ltd BMW	Supply & Fit - N/S Front - Pirelli 225/40 R19 93Y P Zero PZ4 XL RF *
Odo Reading	91723	Supply & Fit - N/S Rear - Pirelli 255/35 R19 96Y P Zero * Run Flat
Invoice No.	TYI24040300017	
Authority Ref.	8835335	Supply & Fit - O/S Rear - Pirelli 255/35 R19 96Y P Zero * Run Flat
Job Ref.	134080108	
Job Status	Settlement Requested	

Date	Service Centre	Line Item Description
18 Mar 2024	Halliwell Jones (Chester) Ltd BMW	Turbocharger - Remove & Refit, Turbocharger gasket
Odo Reading	91723	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:21 Feb 2024 Certificate No:422820091424
Invoice No.	25245900	
Authority Ref.	8842379	Service - Standard Scope - 2011/19 3 Series (F30/F34/F31)
Job Ref.	134024046	brake fluid service - 2011/19 3 Series (F30/F34/F31)
Job Status	Payment Requested	Front Alignment - Check & Adjust, Alignment - toe- in/out (Front Susp.)
		Checks - Check, Investigate & Report
		rear brake service - 2011/19 3 Series (F30/F34/F31)
		Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s
		Automatic Transmission Assembly - Remove & Refit, Oil pan (Auto. Trans.)