

**Service receipts**

<b>Longlife Service:</b>	YES	NO
<b>Service dependent on time/distance travelled</b>	<input type="checkbox"/>	<input type="checkbox"/>
<b>Oil change service</b>	<input type="checkbox"/>	<input type="checkbox"/>
<b>Inspection</b>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Without oil change	<input type="checkbox"/>	<input type="checkbox"/>
With oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<b>Additional tasks</b>	YES	NO
Dust and pollen filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Fuel filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Spark plugs	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake fluid	<input type="checkbox"/>	<input checked="" type="checkbox"/>
DSG@: oil and filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Date: **22-9-15**

Km/Miles: **18,632**

Invoice number: **066586**

Repair recommendation:

Service carried out by:

SEAT technical stamp

Swindon SEAT  
Dorcan Way  
Swindon  
SN3 3RA  
Tel: 01793 414200

Next service due:

Date:


Km/Miles:

(whichever is first)

**Note**

We recommend that you visit a SEAT Official Service whenever you require any work done on your vehicle. Scrupulously following the Services (oil, inspection) at a SEAT Official Service can increase the value of your vehicle.

**Proof of bodywork check (regarding corrosion)**



**Fig. 1 For all vehicles and types of bodywork.**

Your specialised workshop marks damaged parts in the image with following symbols:

- Scratch
- Dent
- Damage to paintwork
- Dent from stone

Service receipts

LongLife Service:	YES	NO
Service dependent on time/distance travelled	<input type="checkbox"/>	<input type="checkbox"/>
Oil change service	<input type="checkbox"/>	<input type="checkbox"/>
Inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Without oil change	<input type="checkbox"/>	<input type="checkbox"/>
With oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Additional tasks	YES	NO
Dust and pollen filter	<input checked="" type="checkbox"/>	ATF
Air filter	<input type="checkbox"/>	HALDEX clutch (oil)
Fuel filter	<input type="checkbox"/>	Gas filter and hoses
Spark plugs	<input checked="" type="checkbox"/>	Liquid gas filter (paper filter)
Brake fluid	<input type="checkbox"/>	Timing belt
DSG®: oil and filter	<input checked="" type="checkbox"/>	

Date

28-9-16

Km/Miles:

359915

Invoice number:

Repair recommendation:

Service carried out by:

**SEAT**  
 Swindon SEAT  
 Dorcan Way  
 Swindon  
 SN1 3RA  
 Tel: 01793 414200  
 Dealer 4765T  
 Technician Stamp

Next service due:

Date: (if different to next page, please enter date of next service)

Km/Miles:

(whichever is first)

Note

We recommend that you visit a SEAT Official Service whenever you require any work done on your vehicle. Scrupulously following the Services (Oil, Inspection) at a SEAT Official Service can increase the value of your vehicle.

Proof of bodywork check (regarding corrosion)




Fig. 2 For all vehicles and types of bodywork.

Your specialised workshop marks damaged parts in the image with the following symbols:

- Scratch
- Dent
- Damage to paintwork
- Dent from stone

Have any faults been detected

Description of faults:

Service receipts

Longlife Service:	YES	NO
Service dependent on time/distance travelled	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Without oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>
With oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Additional tasks	YES	NO
Dust and pollen filter	<input checked="" type="checkbox"/> ATF	<input type="checkbox"/>
Air filter	<input checked="" type="checkbox"/> HALDEX clutch (oil)	<input type="checkbox"/>
Fuel filter	<input checked="" type="checkbox"/> gas filter and hoses	<input type="checkbox"/>
Spark plugs	<input checked="" type="checkbox"/> Liquid gas filter (paper filter)	<input type="checkbox"/>
Brake fluid	<input checked="" type="checkbox"/> Timing belt	<input type="checkbox"/>
DSC@: oil and filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Date: 06/10/17  
 Km/Miles: 50939

Repair recommendation:  
 Service carried out by:

**Fish Brothers**  
**SEAT**  
 Paddington Drive  
 Swindon SN5 7SB  
 Tel.: 01793 645504  
 Dealer 476FY  
 Technical Service Stamp

Next service due:  
 Date:   
 Km/Miles: (whichever is first)

Note

We recommend that you visit a SEAT Official Service whenever you require any work done on your vehicle. Scrupulously following the Services (oil, inspection) at a SEAT Official Service can increase the value of your vehicle.

1 service 14/03/19 @ 57886km AUD ENGINE TUNE

Proof of bodywork check (regarding corrosion)




Fig. 3 For all vehicles and types of bodywork.

Your specialised workshop marks damaged parts in the image with the following symbols:

- Scratch
- Dent
- Damage to paintwork
- Dent from stone

Have any faults been detected?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of faults:	Technical Service Stamp	



Service receipts

Longlife Service:	YES	NO
Service dependent on time/distance travelled	<input type="checkbox"/>	<input type="checkbox"/>
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inspection	<input type="checkbox"/>	<input type="checkbox"/>
Without oil change	<input type="checkbox"/>	<input type="checkbox"/>
With oil change	<input type="checkbox"/>	<input type="checkbox"/>
Additional tasks	YES	NO
Dust and pollen filter	<input type="checkbox"/>	<input type="checkbox"/>
Air filter	<input type="checkbox"/>	<input type="checkbox"/>
Fuel filter	<input type="checkbox"/>	<input type="checkbox"/>
Spark plugs	<input type="checkbox"/>	<input type="checkbox"/>
Brake fluid	<input type="checkbox"/>	<input type="checkbox"/>
DSG® oil and filter	<input type="checkbox"/>	<input type="checkbox"/>
	ATF	
	HAIDEX clutch (oil)	
	Gas filter and hoses	
	Liquid gas filter (paper filter)	
	Timing belt	

Date: 21/6/2021

Km/Miles: 84586

Invoice number: 84586

Repair recommendation:

Service carried out by:

LODGE HILL GARAGE  
OXFORD ROAD  
ABINGDON  
OX14 2JD  
TEL: 01865 920066

Next service due:

Date: (if time dependent, when next service due)

Km/Miles: (whichever is first)

**Note**  
We recommend that you visit a SEAT Official Service whenever you require any work done on your vehicle. Scrupulously following the Services (oil, inspection) at a SEAT Official Service can increase the value of your vehicle.

Proof of bodywork check (regarding corrosion)




Fig. 5 For all vehicles and types of bodywork.

Your specialised workshop marks damaged parts in the image with the following symbols:

- X Scratch
- O Dent
- Damage to paintwork
- △ Dent from stone

Have any faults been detected?

Description of faults:

Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Technical Service Stamp	

Service receipts

Longlife Service:	YES	NO	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Service dependent on time/distance travelled	YES	NO	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Oil change service	YES	NO	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inspection	YES	NO	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Without oil change	YES	NO	<input type="checkbox"/>	<input checked="" type="checkbox"/>
With oil change	YES	NO	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Additional tasks	YES	NO	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Dust and pollen filter	YES	NO	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Air filter	YES	NO	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fuel filter	YES	NO	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Spark plugs	YES	NO	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake fluid	YES	NO	<input type="checkbox"/>	<input checked="" type="checkbox"/>
DSG® oil and filter	YES	NO	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Date: 06-02-22

Km/Miles: 94 397

Invoice number:

Repair recommendation: N/A

Service carried out by: D. Hall

Formula One Autocentres  
Technical Service Stamp

Next service due:

Date: (date when oil change, inspection either gas/oil, liquid gas filter, spark plug, timing belt, etc. is due)

Km/Miles:

(whichever is first)

Note

We recommend that you visit a SEAT Official Service whenever you require any work done on your vehicle. Scrupulously following the Services (oil, inspection) at a SEAT Official Service can increase the value of your vehicle.

Proof of bodywork check (regarding corrosion)




Fig. 6 For all vehicles and types of bodywork.

Your specialised workshop marks damaged parts in the image with the following symbols:

- X Scratch
- Dent
- Damage to paintwork
- △ Dent from stone

Have any faults been detected?		Yes: <input type="checkbox"/>	No: <input checked="" type="checkbox"/>
Description of faults:	(only if necessary)	left side	right side
		<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>
Technical Service Stamp			



Service receipts

Longlife Service:	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
Service dependent on time/distance travelled	<input type="checkbox"/>	<input type="checkbox"/>
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Without oil change	<input type="checkbox"/>	<input type="checkbox"/>
With oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Additional tasks	YES <input type="checkbox"/>	NO <input type="checkbox"/>
Dust and pollen filter	<input checked="" type="checkbox"/>	ATF <input type="checkbox"/>
Air filter	<input checked="" type="checkbox"/>	HADEX clutch (oil) <input type="checkbox"/>
Fuel filter	<input checked="" type="checkbox"/>	Gas filter and hoses <input type="checkbox"/>
Spark plugs	<input type="checkbox"/>	Liquid gas filter (paper filter) <input type="checkbox"/>
Brake fluid	<input checked="" type="checkbox"/>	Timing belt <input type="checkbox"/>
DSG®: oil and filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Date: 22/11/23

Km/Miles: 11413

Invoice number: 500965514

Repair recommendation:

Service carried out by: HALL-1



Next service due:

Date: (which ever is first)

Km/Miles:

Note

We recommend that you visit a SEAT Official Service whenever you require any work done on your vehicle. Scrupulously following the Services (oil inspection) at a SEAT Official Service can increase the value of your vehicle.

Proof of bodywork check (regarding corrosion)




Fig. 8 For all vehicles and types of bodywork.

Your specialised workshop marks damaged parts in the image with the following symbols:

- Scratch
- Dent
- Damage to paintwork
- Dent from stone

Have any faults been detected?		Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of faults:	Head restraint		Seat belt
Technical Service Stamp			



Service receipts

Longlife service:	YES	NO
Service dependent on time/distance travelled	<input type="checkbox"/>	<input type="checkbox"/>
Oil change service	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inspection	<input type="checkbox"/>	<input type="checkbox"/>
Without oil change	<input type="checkbox"/>	<input type="checkbox"/>
With oil change	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<b>Additional tasks</b>	YES	NO
Dust and pollen filter	<input type="checkbox"/>	AF <input type="checkbox"/>
Air filter	<input checked="" type="checkbox"/>	HALDEX clutch (oil) <input type="checkbox"/>
Fuel filter	<input type="checkbox"/>	Gas filter and hoses <input type="checkbox"/>
Spark plugs	<input type="checkbox"/>	Liquid gas filter (paper filter) <input type="checkbox"/>
Brake fluid	<input type="checkbox"/>	Timing belt <input type="checkbox"/>
DSG® oil and filter	<input type="checkbox"/>	<input type="checkbox"/>

Date: 13/6/25  
 Km/Miles: 134064

Invoice number:

Repair recommendation:

Service carried out by:

*[Signature]*

Technical Service Stamp

Next service due:

Date:

Km/Miles:

Eden Bracknell  
 Unit 10/11 Billion Ind Estate  
 Lechliffe, Lechliffe, Lechliffe

Note

We recommend that you visit a SEAT Official Service whenever you require any work done on your vehicle. Scrupulously following the Services (oil, in-spection) at a SEAT Official Service can increase the value of your vehicle.

Proof of bodywork check (regarding corrosion)




Fig. 10 For all vehicles and types of bodywork.

Your specialised workshop marks damaged parts in the image with the following symbols:

- Scratch
- Dent
- Damage to paintwork
- Dent from stone

Description of faults:	Have any faults been detected?	
	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Scratch	<input type="checkbox"/>	<input type="checkbox"/>
Dent	<input type="checkbox"/>	<input type="checkbox"/>
Damage to paintwork	<input type="checkbox"/>	<input type="checkbox"/>
Dent from stone	<input type="checkbox"/>	<input type="checkbox"/>

Technical Service Stamp

04/18 Rear pads + shock abs.  
09/19 Front pads + shock abs  
08/21 Battery - New 5yr guarantee  
11/22 New Glutten  
04/23 Timing belt - New  
05/23 Brake pads (Rear)  
08/23 Air con service  
01/24 New heater matrix

SEAT S.A. is permanently concerned about continuous development of its types and models. For this reason we ask you to understand, that at any given time, changes regarding shape, equipment and technique may take place on the car delivered. For this reason no right at all may derive based on the data, drawings and descriptions in this current handbook.

All texts, illustrations and standards in this handbook are based on the status of information at the time of printing. Except for error or omission, the information included in the current handbook is valid as of the date of closing print.

Re-printing, copying or translating, whether total or partial is not allowed unless SEAT allows it in written form.

SEAT reserves all rights in accordance with the "Copyright" Act.

All rights on changes are reserved.

✿ This paper has been manufactured using bleached non-chlorine cellulose.

© SEAT S.A. - Reprint: 15.05.14