

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

WMWZB32060WL91536

②a Registration number ②b Country of registration

LC61URB

GB

Make and model

MINI MINI (R60)

⑤ Vehicle category

M1

④ Mileage

93,342 miles

Mileage history

87,604 miles 01.08.2024

82,616 miles 01.08.2023

75,281 miles 14.04.2022

⑦ **Pass with defects**

⑥ **Repair as soon as possible (minor defects)**

- Drive shaft joint constant velocity boot severely deteriorated Nearside Front Outer [6.1.7 (g) (i)]

✓ *See receipt*

Monitor and repair if necessary (advisories)

- Coil spring corroded Offside Rear [5.3.1 (b) (i)]

✓ *See receipt.*

③b Date of the test

30.07.2025

⑧ Expiry date

31.07.2026

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 01.07.2026.

③a Location of the test

MAIN ROAD, LONG HANBOROUGH, WITNEY, OX29 8LA

⑨ Testing organisation and inspector name

**92316 NORTH OXFORD GARAGE LIMITED
G. J. Cannon**

MOT test number

4170 4151 4117

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

Issuer signature

North Oxford Garage

MINI Retailer

MINI SERVICE



www.berkshireusedcars.co.uk

E INV



www.berkshireusedcars.co.uk

You were served by:
Chris Jordan

Reg No.:
LC61URB

Vehicle Description:
R60 Cooper Countryman

Date & Tax Point:
30/07/2025

Chassis No.:
WMWZB32060WL91536

Mileage:
93343

WIP No.:
30782

Document No.:
45022189

Account No.:
C0007

Order No.:

Page No.:
1

We Want Your MINI! Up to 7 years old/60,000 miles
Please call our Company Buyer Pete Jackson on 07769 258800

Description of Goods / Services	Qty.	Unit Price	AW	Total
MOT £45				
J MOT			12.00	45.00 E
Carry Out MOT Test £45				
			Subtotal:	45.00
OSR Suspension				
A VHCOSRSUSPENSION			0.00	0.00 S
OSR shock absorber severely leaking, OSR spring co £224.64				
A 3352100			5.00	72.92 S
Remove and install left or right rear spring strut asse				
X M33.52.9.807.016*	1.00@	106.11	0.00	106.11 S
X B33.17.6.760.342*	1.00@	7.01	0.00	7.01 S
X M33.52.6.773.882*	1.00@	1.16	0.00	1.16 S
			Subtotal:	187.20
Vehicle Health Check (VHC)				
T VHCR			0.00	0.00 S
Carried out Free of Charge Vehicle Health Check				
			Subtotal:	0.00

Goods marked with "*" were imported by: BMW UK Ltd, Summit One, Summit Avenue, Farnborough, GU14 0FB, England

Parts	114.28	V	Rate	Service/Goods	V.A.T.	Net	232.20
Surcharge	0.00	E	0.00	45.00	0.00	V.A.T.	37.44
Labour	117.92	S	20.00	187.20	37.44	Total	269.64
Sublet	0.00					Paid	0.00
Menus	0.00					Owing	269.64
E & O. E.							

COMPANY North Oxford Garage Ltd
 POSTAL ADDRESS North Oxford Garage, Main Road, Long Hanborough, Oxford OX29 8LA
 TELEPHONE 01865 319099
 EMAIL mini.reception@oxfordmini.co.uk
 INTERNET www.oxfordmini.co.uk
 REGISTERED OFFICE Wollaston Motors, Bedford Road, Northampton NN1 5SZ
 REGISTERED IN ENGLAND AND WALES 399428 VAT NO. GB 490 8767 96
 Authorised and regulated by the Financial Conduct Authority for credit broking activities