



FIRST YEAR BODY INSPECTION

This portion to be completed and retained in the booklet

Your vehicle's next Body Service is due on:

23/11/2023

Servicing Dealer

78241

A/C No.

Signed

[Signature]

Date

23/11/2022



Celtic Subaru
Victoria Road
Swansea
SA4 3AB
Tel:- 01792 301100
Dealer 78241

Damaged body work which has caused or may cause external corrosion has been noted below and should be rectified promptly.

Defect Code

--	--	--	--	--	--	--	--	--	--

Area Code

--	--	--	--	--	--	--	--	--	--

Customer's Signature

YEAR 1 STANDARD BODY INSPECTION

1) ENSURE UNDERBODY IS THOROUGHLY CLEANED

2) FLOOR LEVEL INSPECTION

• Examine the vehicle to verify that there are no signs of damage or blistering. Any areas that are damaged or show signs of flaking should be retreated. Pay particular attention to the following areas and ensure that all drainage points are clear.

- INSIDE DOORS
- BONNET
- DOORS
- OVER WHEELARCHES
- HEADLIGHT AREA
- BOX SECTIONS
- BOOTLID
- DOOR PILLARS

3) RECORD ANY EXTERNAL PAINT DAMAGE



SECOND YEAR BODY INSPECTION

This portion to be completed and retained in the booklet

Your vehicle's next Body Service is due on:

11/10/24

Servicing Dealer

78241

A/C No.

Signed



SUBARU

Celtic Subaru
Victoria Road
Swansea Dealer Stamp
SA4 3AB
Tel:- 01792 301100
Dealer 78241

Date

11/10/23

Damaged body work which has caused or may cause external corrosion has been noted below and should be rectified promptly.

Defect Code

--	--	--	--	--	--	--	--	--	--

Area Code

--	--	--	--	--	--	--	--	--	--

Customer's Signature

YEAR 2 STANDARD BODY INSPECTION

- 1) ENSURE UNDERBODY IS THOROUGHLY CLEANED
- 2) FLOOR LEVEL INSPECTION
 - Examine the vehicle to verify that there are no signs of damage or blistering. Any areas that are damaged or show signs of flaking should be retreated. Pay particular attention to the following areas and ensure that all drainage points are clear.
 - INSIDE DOORS · HEADLIGHT AREA
 - BONNET · BOX SECTIONS
 - DOORS · BOOTLID
 - OVER WHEELARCHES · DOOR PILLARS
- 3) RECORD ANY EXTERNAL PAINT DAMAGE



THIRD YEAR BODY INSPECTION

This portion to be completed and retained in the booklet

Your vehicle's next Body Service is due on:

4/8/2025

Servicing Dealer

CELTIC

A/C No.

78241

Signed

Date

5/8/24



SUBARU

Celtic Subaru

Victoria Road
Swansea
SA4 3AB
Tel:- 01792 301100
Dealer 78241

YEAR 3 STANDARD BODY INSPECTION

- 1) ENSURE UNDERBODY IS THOROUGHLY CLEANED
- 2) FLOOR LEVEL INSPECTION
 - Examine the vehicle to verify that there are no signs of damage or blistering. Any areas that are damaged or show signs of flaking should be retreated. Pay particular attention to the following areas and ensure that all drainage points are clear.
 - INSIDE DOORS
 - BONNET
 - DOORS
 - OVER WHEELARCHES
 - HEADLIGHT AREA
 - BOX SECTIONS
 - BOOTLID
 - DOOR PILLARS
- 3) RECORD ANY EXTERNAL PAINT DAMAGE

Damaged body work which has caused or may cause external corrosion has been noted below and should be rectified promptly.

Defect Code

<input type="text"/>																			
----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------

Area Code

<input type="text"/>																			
----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------	----------------------

Customer's Signature



FOURTH YEAR BODY INSPECTION

This portion to be completed and retained in the booklet

Your vehicle's next Body Service is due on:

30/7/28

Servicing Dealer

78241

A/C No.

CCUTC

Signed



SUBARU

Date

30/7/25

Dealer Stamp
Celtic Subaru
Victoria Road
Swansea
SA4 3AB
Tel:- 01792 301100
Dealer 78241

Damaged body work which has caused or may cause external corrosion has been noted below and should be rectified promptly.

Defect Code

--	--	--	--	--	--	--	--	--	--

Area Code

--	--	--	--	--	--	--	--	--	--

Customer's Signature

YEAR 4 STANDARD BODY INSPECTION

- 1) ENSURE UNDERBODY IS THOROUGHLY CLEANED
- 2) FLOOR LEVEL INSPECTION
 - Examine the vehicle to verify that there are no signs of damage or blistering. Any areas that are damaged or show signs of flaking should be retreated. Pay particular attention to the following areas and ensure that all drainage points are clear.
 - INSIDE DOORS
 - BONNET
 - DOORS
 - OVER WHEELARCHES
 - HEADLIGHT AREA
 - BOX SECTIONS
 - BOOTLID
 - DOOR PILLARS
- 3) RECORD ANY EXTERNAL PAINT DAMAGE