


## Vehicle data

1	WVWZZZ7N Z HV240231											
2	7N2 35Y											
3	SHARAN						CLBMT					
3	110 KW CRD6F											
3	DFL						SFB					
4	LH5X L--- L--- BY											
	B0N C2L G1A H09 J4E DN4											
	1AT 1G8 1XX 5RV 5SJ											
	351 3U4 QI6 I7A 8QV											
	1LW 3FA 7MM											
	4UP 4X4 4K3 N2N 5MJ											
	BRM 2JC E0A											
	1D0 ABC 8ID USB 1N3 3PG 4A0 8N3											

Fig. 1 1: Vehicle identification number; 2: Vehicle type, engine power, gearbox type; 3: Engine code, gearbox code, paint number, interior equipment; 4: Optional extras, PR numbers.

Delivery inspection carried out on: <u>09/06/17</u>  210 430 Inchcape Volkswagen Swindon Frankland Road Swindon Wiltshire SN5 8YG Tel: 01793 600010	Date of delivery to customer / initial registration: <sup>a)</sup> <u>16/6/17</u> Volkswagen dealership stamp
---	--

a) Whichever comes first.

## The Volkswagen service

### Which vehicles does this service schedule cover?

This service schedule covers the following vehicles:

- CC	- Jetta	- Sharan
- Golf	- Passat	- The Beetle
- Golf GTD	- Passat GTE	- The Beetle
- Golf GTE	- Passat Estate	- Tiguan
- Golf GTI	- Passat Estate GTE	- Touareg
- Golf SV	- Polo	- Touran
- Golf Estate	- Scirocco	- up!

### The importance of this service schedule

The vehicle data (Fig. 1) attached to the inside cover of this service schedule help ensure that you can have the correct Volkswagen Genuine Parts<sup>®</sup> installed in your vehicle whenever required. They also determine which type of service applies to your vehicle.

- The service schedule confirms when the vehicle was first registered or delivered, when the delivery inspection was carried out, and thus the date from which your vehicle is covered by our warranty.
- The service schedule informs you when which service is due. The work to be carried out varies from vehicle to vehicle, but a qualified workshop will be able to explain exactly what work needs to be done.
- Your qualified workshop will document any service-related work in the service schedule.

Your service schedule should be kept in the vehicle wallet to ensure that it is at hand when you need it.

Please remember to give the new owner if you sell your

### WARNING

Inadequate servicing, no sure to adhere to service breakdowns, accidents or


- Have your car serviced shop.
- Observe the owner's m

### NOTICE

Volkswagen is not responsible for damage caused by low-quality standard, inadequate service availability of parts.

Regular servicing maintains its value, vehicle remains roadworthy. Servicing work should be carried out in accordance with the instructions of your qualified workshop.

### Proof of service 1

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input type="checkbox"/> / <input checked="" type="checkbox"/> Oil change service	<input checked="" type="checkbox"/> / <input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> / <input type="checkbox"/> With oil change	<input type="checkbox"/> / <input checked="" type="checkbox"/> Diesel fuel filter
<input checked="" type="checkbox"/> / <input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> / <input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input checked="" type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> / <input checked="" type="checkbox"/> Poly V-belt
<input type="checkbox"/> / <input checked="" type="checkbox"/> Check of headlight settings	<input type="checkbox"/> / <input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> / <input checked="" type="checkbox"/> Repairs recommended	<input type="checkbox"/> / <input checked="" type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> / <input type="checkbox"/> Customer request (this should also be noted on the order)	<input checked="" type="checkbox"/> / <input type="checkbox"/> Dust and pollen filter insert
Service carried out on: 17/4/19	<input type="checkbox"/> / <input checked="" type="checkbox"/> Toothed belt
at km/miles: 16422	<input type="checkbox"/> / <input type="checkbox"/> Spark plugs
Invoice number: 60110	<input type="checkbox"/> / <input type="checkbox"/> .....
Service carried out by: 	LongLife mobility guarantee:
210 094 Lookers VW Battersea 44 Weir Road Wimbledon London SW19 8UG Tel: 020 7924 5544	Volkswagen dealership stamp

Your next services	
Service event	Additional work
<input type="checkbox"/> as per Service interval display	.....
or	.....
on (Date): 17/4/20	on (Date): .....
or	or
at (km/miles): 26422	at (km/miles): .....

### Documentation of the body check




Fig. 3 Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 3 using the following symbols:

- ✕ Scratches      ○ Dents      □ Corrosion      △ Stone chipping

Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of damage:		

Stamp of qualified workshop

3G00127205E

**Proof of service 2**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input checked="" type="checkbox"/> Brake fluid
<input type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input type="checkbox"/> Check of headlight settings	<input type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>30.000 Miles</b>	<input type="checkbox"/> Toothed belt
at km/miles: <b>22410</b>	<input type="checkbox"/> Spark plugs
Invoice number: <b>104.07.20</b>	<input type="checkbox"/> .....
Service carried out by: <b>Lookers VW Battersea</b>	<input type="checkbox"/> .....
<b>210 094</b> Lookers VW Battersea 44 Weir Road Wimbledon London SW19 8UG Tel: 020 7924 5544	<b>LongLife mobility guarantee:</b> <b>210 094</b> Lookers VW Battersea 44 Weir Road Wimbledon London SW19 8UG Tel: 020 7924 5544 Volkswagen dealership stamp

Your next services	
Service event	Additional work
<input type="checkbox"/> as per Service interval display or on (Date): .....	..... on (Date): .....
or at (km/miles): .....	or at (km/miles): .....

**Documentation of the body check**




Fig. 4 Illustration valid for all vehicles and body designs.


Your qualified workshop will indicate damage in Fig. 4 using the following symbols:

- ✕ Scratches
- Dents
- Corrosion
- △ Stone chipping

Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of damage:		
	Stamp of qualified workshop	

3G001.27.05E

**Proof of service 3**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> / <input type="checkbox"/> Oil change service	<input type="checkbox"/> / <input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> / <input type="checkbox"/> Inspection	<input type="checkbox"/> / <input type="checkbox"/> Brake fluid
<input type="checkbox"/> / <input type="checkbox"/> With oil change	<input type="checkbox"/> / <input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> / <input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> / <input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> / <input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> / <input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> / <input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> / <input type="checkbox"/> Poly V-belt
<input type="checkbox"/> / <input type="checkbox"/> Check of headlight settings	<input type="checkbox"/> / <input type="checkbox"/> Air filter insert
<input type="checkbox"/> / <input type="checkbox"/> Repairs recommended	<input type="checkbox"/> / <input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> / <input type="checkbox"/> Customer request (this should also be noted on the order)	<input checked="" type="checkbox"/> / <input type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>23.06.21</b>	<input type="checkbox"/> / <input type="checkbox"/> Toothed belt
at km/miles: <b>29,091</b>	<input type="checkbox"/> / <input type="checkbox"/> Spark plugs
Invoice number: 	<input checked="" type="checkbox"/> / <input type="checkbox"/> <b>A/C Service</b>
Service carried out by: <b>193</b> Lookers VW Wimbledon 44 Weir Road Wimbledon London SW19 8UG Tel: 020 8685 5510	LongLife mobility guarantee:
Stamp of qualified workshop	Volkswagen dealership stamp

Your next services	
Service event	Additional work
<input type="checkbox"/> as per Service interval display or on (Date): ..... or at (km/miles): .....	..... on (Date): ..... or at (km/miles): .....

**Documentation of the body check**




Fig. 5 Illustration valid for all vehicles and body designs.


Your qualified workshop will indicate damage in → Fig. 5 using the following symbols:  
 ✕ Scratches      ○ Dents      □ Corrosion      △ Stone chipping

Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of damage:		

Stamp of qualified workshop

3600117205E

**Proof of service 4**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input checked="" type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input checked="" type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input checked="" type="checkbox"/> Check of headlight settings	<input type="checkbox"/> Air filter insert
<input checked="" type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input checked="" type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on: 29-05-22	<input checked="" type="checkbox"/> Toothed belt
at km/miles: 35516	<input checked="" type="checkbox"/> Spark plugs
Invoice number: 	<input checked="" type="checkbox"/> ALC.....
Service carried out by: 210 193 Lookers VW Wimbledon 44 Weir Road Wimbledon London SW19 8UG Tel: 020 8685 5510	LongLife mobility guarantee:
Stamp of qualified workshop	Volkswagen dealership stamp

Your next services	
Service event	Additional work
<input type="checkbox"/> as per Service Interval display	.....
or	on (Date): .....
on (Date): 05/23	or
or	at (km/miles): .....
at (km/miles): 45516	

**Documentation of the body check**




Fig. 6 Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in → Fig. 6 using the following symbols:  
 ✕ Scratches      ○ Dents      □ Corrosion      ▲ Stone chipping

Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of damage:		

Stamp of qualified workshop



**Proof of service 6**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input type="checkbox"/> Inspection	<input checked="" type="checkbox"/> Brake fluid
<input type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input type="checkbox"/> Check of headlight settings	<input type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on:	<input type="checkbox"/> Toothed belt
at km/miles: <b>57630</b>	<input type="checkbox"/> Spark plugs
Invoice number: <b>07904</b>	<input type="checkbox"/> .....
Service carried out by: <b>Fallsbrook Motors</b>	LongLife mobility guarantee:
<b>STREATHAM SN16 6PX</b>	<i>See receipt.</i>
<b>020 8769 1184</b>	Volkswagen dealership stamp
Stamp of qualified workshop	

Your next services	
Service event	Additional work
<input type="checkbox"/> as per Service interval display or	.....
on (Date): .....	on (Date): .....
or	or
at (km/miles): .....	at (km/miles): .....

**Documentation of the body check**




Fig. 8 Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 8 using the following symbols:

- ✱ Scratches
- Dents
- Corrosion
- △ Stone chipping

Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>	
Description of damage:			Stamp of qualified workshop

**Proof of service 7**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> With oil change	<input checked="" type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input type="checkbox"/> Check of headlight settings	<input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input checked="" type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>19/12/25.</b>	<input type="checkbox"/> Toothed belt
at km/miles: <b>64220</b>	<input type="checkbox"/> Spark plugs
Invoice number: <b>110995.</b>	<input type="checkbox"/> .....
Service carried out by: <b>Fallsbrook Motors</b> <b>STREATHAM SH16 6DY.</b> <b>020 8769 1184.</b> Stamp of qualified workshop	LongLife mobility guarantee:  <b>See receipt.</b> Volkswagen dealership stamp

**Your next services**

Service event	Additional work
<input type="checkbox"/> as per Service interval display or on (Date): ..... or at (km/miles): .....	..... on (Date): ..... or at (km/miles): .....

**Documentation of the body check**




Fig. 9 Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 9 using the following symbols:  
 ✕ Scratches      ○ Dents      □ Corrosion      △ Stone chipping

Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of damage:		
	Stamp of qualified workshop	

3G0012705E