

	Service Centre	Line Item Description
07 Jul 2016	Mercedes-Benz Of Salisbury	Windscreen wiper - blade/s
Odo Reading	17347	Tailgate wiper - blade
Invoice No.	31032	Manufacturer Service - Distance Based
Authority Ref.	6212547	
Job Ref.	78342043	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
22 Apr 2016	ATS CHIPPENHAM (814)	P 1 Wheel Balance
Odo Reading	5329	P 1 Michelin 265/35 R 18 Y S PILOT SPORT PS2
Invoice No.	9181916	XL
Authority Ref.		P 1 Casing Disposal
Job Ref.	3880092	
Job Status	Complete	

	Service Centre	Line Item Description
07 Jul 2016	Mercedes-Benz Of Salisbury	Windscreen wiper - blade/s
Odo Reading	17347	Tailgate wiper - blade
Invoice No.	31032	Manufacturer Service - Distance Based
Authority Ref.	6212547	
Job Ref.	78342043	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
22 Apr 2016	ATS CHIPPENHAM (814)	P 1 Wheel Balance
Odo Reading	5329	P 1 Michelin 265/35 R 18 Y S PILOT SPORT PS2
Invoice No.	9181916	XL
Authority Ref.		P 1 Casing Disposal
Job Ref.	3880092	
Job Status	Complete	

Service Centre		Line Item Description
07 Jul 2017	Vertu Mercedes Benz Slough	31000 mls/kms Service - 2009/- E-Class Saloon/Estate (212)
Odo Reading	31705	Air cleaner/filter - assy
Invoice No.	07518450	Pads - front (axle set)
Authority Ref.	6571668	Disc - front (pair)
Job Ref.	85158175	AdBlue fluid
Job Status	Payment Requested	

Service Centre		Line Item Description
29 Jun 2017	ATS NEWBURY (005)	P 1 Michelin 245/40 R 18 Y PIL SPT4 XL (CA2-71dB)
Odo Reading	31316	P 1 Casing Disposal
Invoice No.	9742412	P 1 Tubeless Valve
Authority Ref.		P 1 Wheel Balance
Job Ref.	4805606	P 1 Michelin 265/35 R 18 Y PIL SPT4 XL (CA2-71dB)
Job Status	Complete	P 1 Casing Disposal
		P 1 Tubeless Valve
		P 1 Wheel Balance

Service Centre		Line Item Description
16 Nov 2016	Smh Gloucester	Fuel
Odo Reading	22785	
Invoice No.	216717	
Authority Ref.	6319875	
Job Ref.	80798604	
Job Status	Payment Requested	

Service Centre		Line Item Description
16 Nov 2016	SMH Fleet Solutions - Gloucester	Vehicle Movement
Odo Reading	22785	Valet
Invoice No.	216638	Vehicle Storage
Authority Ref.	6319361	
Job Ref.	80789157	
Job Status	Payment Requested	

Service Centre		Line Item Description
24 Oct 2016	Smh Gloucester	Smart Repair
Odo Reading	22714	
Invoice No.	216024	
Authority Ref.	6295804	
Job Ref.	80343979	
Job Status	Payment Requested	

Service Centre		Line Item Description
13 Sep 2016	SMH Fleet Solutions - Gloucester	Vehicle Movement
Odo Reading	22714	MOD 10 weekly COIF safety inspection
Invoice No.	215586	MFL VCD Form (Vehicle Condition Description)
Authority Ref.	6263553	
Job Ref.	79582285	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
17 Jul 2019	ATS CH ARVAL DEALERS	P 1 Michelin 245/40 R 18 Y PIL SPT4 XL (CA2-71dB)
Odo Reading	45717	P 1 Casing Disposal
Invoice No.	10645715	P 1 Wheel Balance
Authority Ref.		P 1 Tubeless Valve
Job Ref.	6753103	P 1 Michelin 245/40 R 18 Y PIL SPT4 XL (CA2-71dB)
Job Status	Complete	P 1 Casing Disposal
		P 1 Wheel Balance
		P 1 Tubeless Valve

Date	Service Centre	Line Item Description
12 Jul 2019	Vertu Mercedes Benz Slough	46500 mls/kms Service - 2009/- E-Class Saloon/Estate (212)
Odo Reading	45659	Filters - Remove & Refit, Fuel filter - complete
Invoice No.	7558644	Air Cleaner - Remove & Refit, Air cleaner/filter - element
Authority Ref.	7362929	Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set)
Job Ref.	98816623	Supply & Fit - O/S Front - Continental 245/40 R 18 Y 93CI245/40Y18SSR3 (Run Flat/GB3-72dB)
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
28 Jan 2019	ATS HOUNSLOW TRUCK (124)	P 1 Continental 265/35 R 18 Y SPTCONT 3M X (EB2-73dB)
Odo Reading	42651	P 1 Casing Disposal
Invoice No.	10503292	P 1 Tubeless Valve
Authority Ref.		P 1 Wheel Balance
Job Ref.	6007270	
Job Status	Complete	

Date	Service Centre	Line Item Description
25 Jan 2019	Vertu Mercedes Benz Slough	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:25 Jan 2019 Certificate No:317872698496
Odo Reading	42650	
Invoice No.	7548907	
Authority Ref.	7180596	
Job Ref.	95430121	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
20 Jul 2018	Vertu Mercedes Benz Slough	2 Year Service - 2009/- E-Class Saloon/Estate (212)
Odo Reading	38596	Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake)
Invoice No.	7538386	
Authority Ref.	6975601	
Job Ref.	92113249	
Job Status	Payment Requested	

Work History

Registration/Fleet ID	OY65WEH	Asset No.	AACP2269
Make/Model	MERCEDES-BENZ E CLASS DIESEL ESTATE (2013) E220 BlueTEC AMG Night Ed Premium 5dr 7G-T		
Latest Odo Reading	50886	Odo Reading Date	01 Feb 2021
Contract Start Date	25 Feb 2016	Contract End Date	24 May 2021

Date	Service Centre	Line Item Description
01 Feb 2021	Vertu Mercedes Benz Slough	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:01 Feb 2021 Certificate No:657438664272
Odo Reading	50886	
Invoice No.	7588560	
Authority Ref.	7853775	
Job Ref.	108560740	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
07 Jan 2021	A A Breakdown	P 1 BOSCH AGM S5A08 (096)
Odo Reading	50186	
Invoice No.	200480289	
Authority Ref.		
Job Ref.	7634294	
Job Status	Complete	

Date	Service Centre	Line Item Description
17 Sep 2020	Vertu Mercedes Benz Slough	4 year Service - 2009/- E-Class Saloon/Estate (212)
Odo Reading	50060	Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake)
Invoice No.	7580620	Ventilation - Remove & Refit, Pollen filter
Authority Ref.	7732871	
Job Ref.	106134752	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
30 Jan 2020	Vertu Mercedes Benz Slough	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:30 Jan 2020 Certificate No:757187661253
Odo Reading	49061	
Invoice No.	7569942	
Authority Ref.	7561089	
Job Ref.	102239426	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
20 Aug 2019	ATS CH ARVAL DEALERS	P 1 Wheel Balance P 1 Tubeless Valve P 1 Casing Disposal P 1 Michelin 265/35 R 18 Y PIL SPT4 XL (CA2-71dB)
Odo Reading	46252	
Invoice No.	10671514	
Authority Ref.		
Job Ref.	6827047	
Job Status	Complete	

Date	Service Centre	Line Item Description
06 Aug 2019	Vertu Mercedes Benz Slough	carry out star test and check for engine warning light on Sensors - Remove & Refit, Sensor - oxygen Water Pump - Remove & Refit, Water pump
Odo Reading	46179	
Invoice No.	7560249	
Authority Ref.	7385819	
Job Ref.	99265812	
Job Status	Payment Requested	

ELITE GARAGE SERVICES LTD
INDEPENDENT SPECIALIST
ALL MAKES AND MODELS
TURNPIKE IND. EST. NEWBURY
01635 551000

19.07.2021

52074

oil Service + Adol blue

6

OJS MOTORS
UNIT 3, WARDS FARM,
WOODCOTE, RG8 0RB
 01184 500000



www.berkshireusedcars.co.uk

Invoice Number: **4596**
 Account Number: PAI003
 Order Ref / Number:
 Invoice Date: 01/07/2022
 Payment Method: PENDING
 Date of Work: 23/06/2022

Registration	Make & Model	Chassis Number	Engine CC	Mileage
OY65WEH	Mercedes E Class			61437

Labour Description	Qty / Hrs	Unit Price	Price
Carry out MOT Test			
Carried out service			
Replaced front pads			
Replaced auxiliary battery			
	3	61.50	184.50
Labour Sub Total			184.50

Parts Description	Part No	Qty	Unit Price	Price
genuine aux battery		1	90.00	90.00
oil		6.5	9.00	58.50
oil filter		1	11.40	11.40
front pads		1	55.11	55.11
sensor		1	6.70	6.70
sundries and waste disposal		1	2.50	2.50
Parts Sub Total				224.21

LABOUR & PARTS	408.71
VAT at 20%	81.74
MOT	54.85
TOTAL DUE	545.30

BANK DETAILS - NATWEST 37629255 54-30-33
 VAT number 321 6533 30
 PAYMENT TO BE MADE IMMEDIATELY

OJS MOTORS

UNIT 3 WARDS FARM

WOODCOTE

RG8 0RB

01491 598570

VAT Registration No : 321653330

www.berkshireusedcars.co.uk**INVOICE NO.** 2226**DATE** 19/06/2024**DUE DATE** 19/06/2024**TERMS** Due on receipt

	QTY	RATE	AMOUNT
Carried out service	1	70.00	70.00
Carried out mot	1	42.00	42.00
mot pre check	1	10.71	10.71
oil	6.50	9.50	61.75
oil filter	1	10.21	10.21
sundries and waste disposal	1	5.00	5.00
Advisories			
- rear pads low			
- o/s/f and both rear tyres soon			
- michelin pilot sport 4, 245/40 18 97y front,			
265/35 18 97y rears			
- Next service is a full service			

OY65WEH
MERCEDES
76331 MILES

SUBTOTAL	199.67
VAT TOTAL	31.53
TOTAL	231.20
BALANCE DUE	£231.20

fuel filter replacement average cost - £114
Air filter replacement av. cost - £60
oil - £100

NATWEST
37629255
54-30-33

PAYMENT TO BE MADE IMMEDIATELY

tyres - £120 x 4 =
+ £480



www.berkshireusedcars.co.uk

Elite Garage Services

Unit 22 Turnpike Ind Est
Turnpike Road
Newbury
Berks
RG14 2LR

Tel: 01635 551000

Email: reception@elite-garage.co.uk • Web: www.elite-garage.co.uk

Invoice I017441

Date: 19-06-2025

Estimate: Q015876

Job: J018176

Vehicle

Registration: OY65WEH

Mercedes Benz E Class E220 2016 2.1 Diesel - BLACK

Mileage: 85677

VIN: WDD2122012B323219

Issues and Work Description

Work Description

MOT = FAILED

- PLEASE SEE CERTIFICATE FOR DEFECTS & ADVISORIES

WORKS:

- STRIPPED AS NECESSARY, DESEIZED AND LUBED GUIDES & PLUNGERS AND SUPPLIED & FITTED NEW 'BREMBO' REAR BRAKE PADS AND ASSOCIATED PAD WEAR SENSOR. BUILT BACK UP, PUT ON SCANNER FOR PAD MODE CHANGE AND TESTED = ALL OK
- SUPPLIED FITTED NEW 'NEXEN' TYRES ALL ROUND COMPLETE WITH VALVES & BALANCING
- REPLACED FRONT WIPER BLADE SET

ANNUAL SERVICE:

- REPLACED OIL FILTER & OIL
- REPLACED POLLEN FILTER
- LIGHTS AND LEVELS CHECK OVER
- ANTI-FREEZE = -37
- TYRE DEPTHS = ALL 4X TYRES ARE NEW
- SERVICE LIGHT RESET
- ROAD TESTED

FOC MOT RE-TEST = PASSED

ADVISORIES:

- FRONT BRAKE PADS WEARING THIN, ADVISE REPLACEMENT IN 4,500 MILES - LIGHT SHOULD COME ON ON DASH
- FRONT BRAKE PADS ARE WORN - REPLACE AT SAME TIME AS PADS (SAVE LABOUR COSTS)
- WE RECOMMEND BRAKE FLUID SERVICES ARE CARRIED OUT EVERY 2X YEARS
- WE RECOMMEND AIR-CONDITIONING SERVICES ARE CARRIED OUT EVERY 2X YEARS

Work performed

Parts

Parts	Part No	Qty	Unit Price	VAT %	Net Total
NEXEN TYRES (FRONT) - SUPPLY & FIT	245/40YR18	2.00	108.00	20.0	216.00
NEXEN TYRES (REAR) - SUPPLY & FIT	265/35R18	2.00	116.66	20.0	233.32
REAR BRAKE PADS (PAIR)	10122071A	1.00	39.88	20.0	39.88
PAD WEAR SENSOR	106220058	1.00	10.26	20.0	10.26
CABIN/POLLEN FILTER	507220759	1.00	33.10	20.0	33.10
OIL FILTER	501220379	1.00	14.52	20.0	14.52
ENGINE OIL 5W/30 6.5LTRS	STOCK	1.00	75.95	20.0	75.95
LUBE & WASTE	ENVIRON	1.00	10.90	20.0	10.90
WIPERBLADE SET	485776520	1.00	40.11	20.0	40.11

Parts SubTotal £674.04



Mercedes-Benz

Digital Service Report

Vehicle info

Vehicle E 220 BlueTEC
First reg. date 25.02.2016
FIN WDD2122012B323219

Next Service 06.2027 109102 mls

(Please note the additional information in your vehicle (owner's manual, service booklet and service interval indicator) on the performance of the next service)

Service report 4

Mercedes-Benz	Sandown Surrey and Hampshire Limited	Date	04.06.2026
	London Road 123	Rep.-order-no.	08-14451
	Newbury	Mileage	93602 mls

Performed services

Service	Service A
Workshop code	5050
Remaining time	15 Days
Remaining distance	8100 mls

Oil quality/viscosity

Description	Engine oil
Oil quality	229.52
Viscosity	

Replaced / renewed

Perform Service A with Plus package	☒
-------------------------------------	-------------------------------------

Until next service

Mercedes-Benz Mobilo	☒
Warr. against rusting through	☒

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with	☐
---------------	--------------------------

Addwork in accordance with Mercedes-Benz AG specification

Accomplished	☒
--------------	-------------------------------------
