

Proof of service 12

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ / ☐ Oil change service	☐ / ☐ AdBlue®
☐ / ☐ In combination	☐ / ☐ Brake fluid
☒ / ☐ Interval service including engine oil change	☐ / ☐ Diesel fuel filter
☐ / ☐ In combination	☐ / ☐ Gas filter
☒ / ☐ Inspection service	☐ / ☐ Gearbox oil: DSG®, ATF
☐ / ☐ LongLife engine oil used	☐ / ☐ Haldex coupling: oil
☐ / ☐ Bodywork checked for protection against corrosion	☐ / ☐ Air filter insert
☐ / ☐ Repairs recommended	☐ / ☐ Tyre filler bottle
☐ / ☐ Customer request (this should also be noted on the order)	☐ / ☐ Dust and pollen filter insert
Service carried out on: 22-9-26	☐ / ☐ Toothed belt
at km/miles: 77,683	☐ / ☐ Spark plugs
Invoice number: 20156	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
ELITE GARAGE SERVICES LTD INDEPENDENT SPECIALIST ALL MAKES AND MODELS TURNPIKE IND. EST. NEWBURY 01635 551000	
Volkswagen dealership stamp	Volkswagen dealership stamp

Your next service	
Is due on (date):	Which service is due next?
or	
at (km/miles):	

Proof of service 11

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ ☐ Oil change service	☐ ☐ AdBlue®
☐ ☐ In combination	☐ ☐ Brake fluid
☒ ☐ Interval service including engine oil change	☐ ☐ Diesel fuel filter
☐ ☐ In combination	☐ ☐ Gas filter
☒ ☐ Inspection service	☐ ☐ Gearbox oil: DSG®, ATF
☒ ☐ LongLife engine oil used	☐ ☐ Haldex coupling: oil
☒ ☐ Bodywork checked for protection against corrosion	☒ ☐ Air filter insert
☐ ☐ Repairs recommended	☐ ☐ Tyre filler bottle
☐ ☐ Customer request (this should also be noted on the order)	☒ ☐ Dust and pollen filter insert
Service carried out on: 8/9/25.	☐ ☐ Toothed belt
at km/miles: 72447	☐ ☐ Spark plugs
Invoice number:	☐ ☐
Service carried out by:	LongLife mobility guarantee:
VIADUCT SERVICE STATION 150 BIRMINGHAM STREET STOURBRIDGE WEST MIDLANDS DY9 7PR 01384 422012 info@viaductservicestation.co.uk	Volkswagen dealership stamp
Volkswagen dealership stamp	Volkswagen dealership stamp
Your next service	
Is due on (date):	Which service is due next?
or	
at (km/miles):	

☒ Oil change service	☐ / ☐ AdBlue®
☒ In combination	☐ / ☐ Brake fluid
☒ Interval service including engine oil change	☐ / ☐ Diesel fuel filter
☐ In combination	☐ / ☐ Gas filter
☒ Inspection service	☐ / ☐ Gearbox oil: DSG®, ATF
☐ LongLife engine oil used	☐ / ☐ Haldex coupling: oil
☒ Bodywork checked for protection against corrosion	☐ / ☐ Air filter insert
☐ Repairs recommended	☐ / ☐ Tyre filler bottle
☐ Customer request (this should also be noted on the order)	☒ / ☐ Dust and pollen filter insert
Service carried out on: 2-9-24	☐ / ☐ Toothed belt
at km/miles: 68262	☐ / ☐ Spark plugs
Invoice number:	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
VIADUCT SERVICE STATION 150 BIRMINGHAM STREET STOURBRIDGE WEST MIDLANDS DY9 7PR 01384 422012 info@viaductservicestation.co.uk	
Volkswagen dealership stamp	Volkswagen dealership stamp

Your next service

Is due on (date):

or

at (km/miles):

Which service is due next?

Proof of service 9

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ / ☒ Oil change service	☐ / ☐ AdBlue®
☒ / ☒ In combination	☐ / ☐ Brake fluid
☒ / ☒ Interval service including engine oil change	☐ / ☐ Diesel fuel filter
☐ / ☐ In combination	☐ / ☐ Gas filter
☐ / ☐ Inspection service	☐ / ☐ Gearbox oil: DSG®, ATF
☐ / ☐ LongLife engine oil used	☐ / ☐ Haldex coupling: oil
☐ / ☐ Bodywork checked for protection against corrosion	☐ / ☐ Air filter insert
☐ / ☐ Repairs recommended	☐ / ☐ Tyre filler bottle
☐ / ☐ Customer request (this should also be noted on the order)	☐ / ☐ Dust and pollen filter insert
Service carried out on: 22108123	☐ / ☐ Toothed belt
at km/miles: 64320	☐ / ☐ Spark plugs
Invoice number:	☐ / ☐
Service carried out by: College Auto & Motor Care Centres Rufford Road, Stourbridge DY9 7NG Tel: 01384 441553/441692 <i>Short service</i> Volkswagen dealership stamp	LongLife mobility guarantee: Volkswagen dealership stamp

Your next service	
Is due on (date): or at (km/miles):	Which service is due next?

Proof of service 8

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ / ☐ Oil change service	☐ / ☐ AdBlue®
☐ / ☒ In combination	☐ / ☐ Brake fluid
☒ / ☐ Interval service including engine oil change	☐ / ☐ Diesel fuel filter
☐ / ☒ In combination	☐ / ☐ Gas filter
☐ / ☒ Inspection service	☐ / ☐ Gearbox oil: DSG®, ATF
☐ / ☒ LongLife engine oil used	☐ / ☐ Haldex coupling: oil
☐ / ☒ Bodywork checked for protection against corrosion	☐ / ☐ Air filter insert
☐ / ☒ Repairs recommended	☐ / ☐ Tyre filler bottle
☐ / ☒ Customer request (this should also be noted on the order)	☐ / ☐ Dust and pollen filter insert
Service carried out on: 03/09/20	☐ / ☐ Toothed belt
at km/miles: 51503	☐ / ☐ Spark plugs
Invoice number:	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
R & M Autotecnica Ltd Hawthorn Avenue Manchester M41 9NP 0161 283 0305	
Volkswagen dealership stamp	Volkswagen dealership stamp


Your next service	
Is due on (date):	Which service is due next?
or	
at (km/miles):	

Proof of service 7

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ / ☐ Oil change service	☐ / ☐ AdBlue®
☐ / ☒ In combination	☐ / ☐ Brake fluid
☒ / ☐ Interval service including engine oil change	☐ / ☐ Diesel fuel filter
☐ / ☐ In combination	☐ / ☐ Gas filter
☐ / ☐ Inspection service	☐ / ☐ Gearbox oil: DSG®, ATF
☐ / ☐ LongLife engine oil used	☐ / ☐ Haldex coupling: oil
☐ / ☐ Bodywork checked for protection against corrosion	☐ / ☐ Air filter insert
☐ / ☐ Repairs recommended	☐ / ☐ Tyre filler bottle
☐ / ☐ Customer request (this should also be noted on the order)	☐ / ☐ Dust and pollen filter insert
Service carried out on: 04-8-20	☐ / ☐ Toothed belt
at km/miles: 49182	☐ / ☐ Spark plugs
Invoice number:	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
 Quality every step of the way www.halfords.com Tel: 0800 096 4216	
Volkswagen dealership stamp	Volkswagen dealership stamp

Your next service	
Is due on (date):	Which service is due next?
or	
at (km/miles):	

Proof of service 6

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ ☐ Oil change service	☐ ☐ AdBlue®
☐ ☒ In combination	☐ ☐ Brake fluid
☒ ☐ Interval service including engine oil change	☐ ☐ Diesel fuel filter
☐ ☐ In combination	☐ ☐ Gas filter
☐ ☐ Inspection service	☐ ☐ Gearbox oil: DSG®, ATF
☐ ☐ LongLife engine oil used	☐ ☐ Haldex coupling: oil
☐ ☐ Bodywork checked for protection against corrosion	☐ ☐ Air filter insert
☐ ☐ Repairs recommended	☐ ☐ Tyre filler bottle
☐ ☐ Customer request (this should also be noted on the order)	☐ ☐ Dust and pollen filter insert
Service carried out on: 29/7/19	☐ ☐ Toothed belt
at km/miles: 44763	☐ ☐ Spark plugs
Invoice number:	☐ ☐
Service carried out by:	LongLife mobility guarantee:
 <i>Quality every step of the way</i> www.halfords.com Tel: 0800 096 4216	
Volkswagen dealership stamp	Volkswagen dealership stamp

Your next service

Is due on (date):

or

at (km/miles):

Which service is due next?

Proof of service 5

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ Oil change service	☐ AdBlue®
☐ In combination	☐ Brake fluid
☒ Interval service including engine oil change	☐ Diesel fuel filter
☐ In combination	☐ Gas filter
☐ Inspection service	☐ Gearbox oil: DSG®, ATF
☐ LongLife engine oil used	☐ Haldex coupling: oil
☐ Bodywork checked for protection against corrosion	☐ Air filter insert
☐ Repairs recommended	☐ Tyre filler bottle
☐ Customer request (this should also be noted on the order)	☐ Dust and pollen filter insert
Service carried out on: 22-8-19	☐ Toothed belt
at km/miles: 39417	☐ Spark plugs
Invoice number:	☐
Service carried out by:	LongLife mobility guarantee:
 halfords Quality every step of the way www.halfords.com Tel: 0800 096 4210	Volkswagen dealership stamp

Your next service	
Is due on (date):	Which service is due next?
or at (km/miles):	

Yes / No. The following work was carried out:	Yes / No. Change of:
☐ / ☐ Oil change service	☐ / ☐ AdBlue®
☐ / ☐ In combination	☐ / ☐ Brake fluid
☐ / ☐ Interval service including engine oil change	☐ / ☐ Diesel fuel filter
☐ / ☐ In combination	☐ / ☐ Gas filter
☐ / ☐ Inspection service	☐ / ☐ Gearbox oil: DSG®, ATF
☐ / ☐ LongLife engine oil used	☐ / ☐ Haldex coupling: oil
☐ / ☐ Bodywork checked for protection against corrosion	☐ / ☐ Air filter insert
☐ / ☐ Repairs recommended	☐ / ☐ Tyre filler bottle
☐ / ☐ Customer request (this should also be noted on the order)	☐ / ☐ Dust and pollen filter insert
Service carried out on: 16/08/17	☐ / ☐ Toothed belt
at km/miles: 32766.	☐ / ☐ Spark plugs
Invoice number: 66919.	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
SOVEREIGN GARAGE LTD HOLMFIRTH ROAD, SHEPLEY HUDDERSFIELD HD8 8BB TEL 01484 606666	
Volkswagen dealership stamp	Volkswagen dealership stamp

Your next service	
Is due on (date):	Which service is due next?
or	
at (km/miles):	

Yes / No. The following work was carried out:	Yes / No. Change of:
☐ / ☐ Oil change service	☐ / ☐ AdBlue®
☐ / ☐ In combination	☐ / ☐ Brake fluid
☐ / ☐ Interval service including engine oil change	☐ / ☐ Diesel fuel filter
☐ / ☐ In combination	☐ / ☐ Gas filter
☐ / ☐ Inspection service	☐ / ☐ Gearbox oil: DSG®, ATF
☐ / ☐ LongLife engine oil used	☐ / ☐ Haldex coupling: oil
☐ / ☐ Bodywork checked for protection against corrosion	☐ / ☐ Air filter insert
☐ / ☐ Repairs recommended	☐ / ☐ Tyre filler bottle
☐ / ☐ Customer request (this should also be noted on the order)	☐ / ☐ Dust and pollen filter insert
Service carried out on: 6/11/15	☐ / ☐ Toothed belt
at km/miles: 19527	☐ / ☐ Spark plugs
Invoice number:	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
The Car People Ltd Calder Island Way Wakefield WF2 7AW TEL 01924887654 FAX: 01924887610	
Volkswagen dealership stamp	Volkswagen dealership stamp


Your next service	
Is due on (date):	Which service is due next?
or	
at (km/miles):	

Proof of service 2

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ / ☐ Oil change service	☐ / ☒ AdBlue®
☐ / ☒ In combination	☐ / ☒ Brake fluid
☒ / ☐ Interval service including engine oil change	☐ / ☒ Diesel fuel filter
☐ / ☒ In combination	☐ / ☒ Gas filter
☒ / ☐ Inspection service	☐ / ☒ Gearbox oil: DSG®, ATF
☒ / ☐ LongLife engine oil used	☐ / ☒ Haldex coupling: oil
☐ / ☒ Bodywork checked for protection against corrosion	☐ / ☒ Air filter insert
☐ / ☒ Repairs recommended	☐ / ☒ Tyre filler bottle
☐ / ☒ Customer request (this should also be noted on the order)	☒ / ☐ Dust and pollen filter insert
Service carried out on: 20-3-15	☐ / ☒ Toothed belt
at km/miles: 12550	☐ / ☒ Spark plugs
Invoice number: 46523	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
 210 323 Indicape Volkswagen 2 Comet Way Southend-on-Sea Essex SS2 6XR Tel: 01702 421142 Fax: 01702 421354	
Volkswagen dealership stamp	Volkswagen dealership stamp

Your next service	
Is due on (date):	Which service is due next?
or	
at (km/miles):	

Proof of service 1

Yes / No. The following work was carried out:	Yes / No. Change of:
☒ / ☐ Oil change service	☐ / ☒ AdBlue®
☐ / ☒ In combination	☐ / ☒ Brake fluid
☐ / ☒ Interval service including engine oil change	☐ / ☒ Diesel fuel filter
☐ / ☒ In combination	☐ / ☒ Gas filter
☐ / ☒ Inspection service	☐ / ☒ Gearbox oil: DSG®, ATF
☐ / ☒ LongLife engine oil used	☐ / ☒ Haldex coupling: oil
☐ / ☒ Bodywork checked for protection against corrosion	☐ / ☒ Air filter insert
☐ / ☒ Repairs recommended	☐ / ☒ Tyre filler bottle
☐ / ☒ Customer request (this should also be noted on the order)	☐ / ☒ Dust and pollen filter insert
Service carried out on: 20-2-14	☐ / ☒ Toothed belt
at km/miles: 4723	☐ / ☒ Spark plugs
Invoice number:	☐ / ☐
Service carried out by:	LongLife mobility guarantee:
 210 323 Inchcape Volkswagen 2 Cornet Way Southend-on-Sea Essex SS2 6XR Tel: 01702 421142 Fax: 01702 421354	Volkswagen dealership stamp

Your next service	
Is due on (date): 2-15	Which service is due next?
or	
at (km/miles): 204	

1		WVWZZZ6RzDY165058															
2		6R1 3B4															
		POLO 1.2 COMFO															
3		44 MSF															
		CGP LNR															
4		LO41 HX															
		1AT Q16 --- ---															
		7MG C4M HW1 4KF 3NC															
		1MH Q1A J2S 9IO 8M1															
		8BK UOL BRL 8TD 8WB															
		BAY ---															

BTT-0507

Fig. 1 1: Vehicle identification number; 2: Vehicle type, engine power, gearbox type; 3: Engine code, gearbox code, paint number, interior equipment; 4: Optional extras, PR numbers

Delivery inspection carried out on: 11-1-13  210 323 Inchcape Volkswagen 2 Cornhill Way Southampton SO14 3JH Econ. US2 CXX Tel: 01702 421142 Fax: 01702 421354	Date of delivery to customer / initial registration:^{a)}
Volkswagen dealership stamp	Volkswagen dealership stamp

^{a)} Whichever comes first