Date	Service Centre	Line Item Description
14 Feb 2024	City Fleet Care Ltd	Manufacturer Service - Time Based
Odo Reading	14873	Checks - Check, Investigate & Report
Invoice No.	067202	
Authority Ref.	8803354	
Job Ref.	133072870	
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
15 Aug 2023	ATS CH ARVAL DEALERS	P 1 Goodyear 215/45 R 17 W EFFIGRIP PERFX (BA1-69dB)
Odo Reading	7812	P 1 Casing Disposal
Invoice No.	11415480	P 1 Wheel Balance
Authority Ref.		P 1 Tubeless Valve
Job Ref.	10521958	
Job Status	Complete	

Date	Service Centre	Line Item Description
30 Jun 2023	CLOSED - Bristol Street SEAT Birmingham	First Service (1link)
Odo Reading	6268	
Invoice No.	10571704	
Authority Ref.	8617362	
Job Ref.	127133600	
Job Status	Payment Requested	

4

Date	Service Centre	Line Item Description
29 Jun 2026	City Fleet Care Ltd	MOT - Class IV Cars (Up To 8 Passenger Seats) Test Date:01 Jul 2026 Certificate No:760229583468
Odo Reading	33207	Checks - Check, Investigate & Report
Invoice No.	6995572	Inspection Service Extended Scope (including Oil Change) - 2021/- Ibiza
Authority Ref.	9534035	Air Cleaner - Remove & Refit, Air cleaner/filter - element
Job Ref.	158555063	Ventilation - Remove & Refit, Pollen filter
Job Status	Payment Requested	Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s
		Abs Components - Remove & Refit, ABS module/hydraulic unit
		Wash/Wipe Systems - Remove & Refit, Tailgate wiper - blade
		Water Pump - Remove & Refit, Water pump
		Checks - Check, Investigate & Report

3

Date	Service Centre	Line Item Description
20 Nov 2025	M K Fleet Services Digbeth	Checks - Check, Investigate & Report
Odo Reading	32209	Mountings - Remove & Refit, Mounting - front (one)
Invoice No.	62720	Inspection Service (including Oil Change) - 2021/- Ibiza
Authority Ref.	9361583	Spark Plugs - Remove & Refit, Spark plugs
Job Ref.	151697607	Ventilation - Remove & Refit, Pollen filter
Job Status	Payment Requested	Flywheel - Remove & Refit, Flywheel/drive plate

Date	Service Centre	Line Item Description
01 May 2025	Halfords Fusion Autocentre Olton (089)	Disc - Remove & Refit, Disc - front (pair)
Odo Reading	32099	Disc - Remove & Refit, Disc - rear (pair)
Invoice No.	089/9021214	Linings (Pads & Shoes) - Remove & Refit, Pads - front (axle set)
Authority Ref.	9189305	Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set)
Job Ref.	145670711	Hydraulic Fluid - Remove & Refit, Hydraulic fluid (Brake)
Job Status	Payment Requested	

Date	Service Centre	Line Item Description
01 May 2025	ITMS247LTD-HALFORDS - Halfords Olton (089)	P 1 Environmental Disposal
Odo Reading	32099	P 1 Tubeless Valve
Invoice No.	SIN1584381	P 1 Alloy Wheel Balance
Authority Ref.		P 1 215/45 17 91W CAR XL GOODYEAR EFFICIENTGRIP PERFORMANCE
Job Ref.	11773789	P 1 Environmental Disposal
Job Status	Complete	P 1 Tubeless Valve
		P 1 Alloy Wheel Balance
		P 1 215/45 17 91W CAR XL GOODYEAR EFFICIENTGRIP PERFORMANCE